Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: 01 - MAIN BUILDING 01 A. BUILDING B. WING TN1803 07/05/2011 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **456 WAYNE AVENUE** WYNDRIDGE HEALTH AND REHAB CTR CROSSVILLE, TN 38555 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (X4) ID ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX **PREFIX** REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) N 832 1200-8-6-.08(2) Building Standards N 832 (2) The condition of the physical plant and the The sprinkler and alarm company, overall nursing home environment must be Simplex Grinnell, was contacted to install developed and maintained in such a manner that new strobe type fire alarm lights in lobby the safety and well-being of residents are bathrooms. This will be monitored by the assured. Director of Plant Operations. 07/21/2011 This Rule is not met as evidenced by: Based on observations, it was determined the facility failed to comply with the Tennessee Department of Health Building Standards. The findings include: Observation of the front lobby handicapped bathrooms on 7/5/11 at 8:55 AM, revealed no strobe lights installed in the bathrooms. This finding was acknowledged by the Administrator and verified by the Director of Maintenance at the exit conference on 7/5/11. Division of Health Care Facilities May (a MA- war, MSH4, WHH # 2680 (X6) DATE Adamiist ato LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE 7.00.00

STATE FORM

IVR421